

NOTES

210

210

- Specifications are subject to change without notice.
- 2 Be sure to provide two inspection hatches (□450 or □600) at the service side of filters and elements
- 3 The high efficiency filter (option) can be attached to the SA surface of the heat exchanger elements.